


ROAD & BRIDGE SAFETY IMPROVEMENT AWARD PROGRAM

PROJECT ENTRY: DODDS ROAD REALIGNMENT & STREAMBANK RESTORATION

Photography



Dodds Road after construction was completed



Improved visibility and turning radii at intersection of Dodds Road and Rockdale Road




BEFORE CONSTRUCTION: Dodds Road was flooded after heavy rains in February 2024.



AFTER CONSTRUCTION: The road remained clear after similar rain and melting snow in February 2025.



BEFORE CONSTRUCTION: Dodds Road was very close to the creek, and visibility at the intersection with Rockdale Road was reduced due to the steep slope of the roadway.



AFTER CONSTRUCTION: The road has been shifted away from the creek.